

PRODUCT SAFETY RECALL

Latitude Milano Bench Seat

Mitre 10 (New Zealand) Ltd is voluntarily recalling the Latitude Milano Bench Seat listed above due to a fault that may cause it to break.

This product was sold between September 2013 – November 2014 at Mitre 10 MEGA stores and selected Mitre 10 stores.



SKU: 202064

This seat can be identified by a badge on the side beam of the seat saying 'Latitude'.

Customers should cease using the bench seat immediately and return the product to their nearest Mitre 10 or Mitre 10 MEGA store. A full refund will be given and replacement options are available to customers.

The address of your nearest Mitre 10 store can be obtained by calling 0800 4 MITRE 10 or by visiting www.mitre10.co.nz/storelocator. For further information and assistance please contact Mitre 10 (New Zealand) Ltd Support Centre via the details below:

Mitre 10 (New Zealand) Limited, Private Bag 102925, North Shore, Auckland 0745
Phone: 0800 800 610 | Email: importsqueries@mitre10.co.nz

Mitre 10 (New Zealand) Ltd apologies for any inconvenience.