

Product Safety Recall



2000W Flat Fan Heater

*Models: Celsius CELFH110 with date code 5016, sold in Countdown in 2017,
Or: Number 8 N8FH120 with date code 5016, sold in Mitre 10 in 2017*

Defect: *If the unit is damaged or suffered a considerable drop, the element may dislodge resulting in the element glowing red, overheating and melting the front of the heater enclosure.*

Hazard: *Surrounding material could possibly catch alight or allow access to electrical components with risk of electric shock.*


What to do:

- 1. Customers should cease using the Heater immediately.*
- 2. Customers should contact Celsius for further information on how to receive a refund or replacement heater.*

Contact details:

*Contact Celsius
0800 232 633 between 8am - 5pm Mon - Fri
Email: recall@celsius.co.nz*

Image of rating label indicating date code location



New Zealand Importer/Distributor

Celsius
P O Box 100 707, NSMC, Auckland
New Zealand
0800 232 633

See www.recalls.govt.nz for
other New Zealand consumer product recalls

Issued: June 2017